

03500.015495



COFC
[Signature]
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	
	:	Examiner: M. Santiago
NORIHIRO SUZUKI, ET AL.)	
	:	Group Art Unit: 2879
Application No.: 09/892,641)	
	:	
Filed: June 28, 2001)	
	:	
For: IMAGE DISPLAY APPARATUS)	January 19, 2006
AND METHOD OF MANUFAC-	:	
TURING THE SAME)	
	:	
U.S. Patent No. 6,840,832 B2)	
	:	
Issued: January 11, 2005)	

Certificate
JAN 24 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

01/20/2006 SZEWDIE1 00000056 6840832

01 FC:1811

100.00 DP

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

JAN 25 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,



Scott D. Malpede
Attorney for Patentees
Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM/vmm

DC_MAIN 197312v1

JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,840,832 B2

DATED : January 11, 2005

INVENTOR(S) : NORIHIRO SUZUKI, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 46, "and" should be deleted.

COLUMN 2:

Line 50, "to cause." should read --from being caused.--.

COLUMN 13:

Line 37, "film" (second occurrence) should read --films--.

COLUMN 14:

Line 43, "width Ti" should read --width T1--.

COLUMN 16:

Line 31, "electrode 1203" should read --electrodes 1203--.

COLUMN 17:

Line 24, "Third. Since" should read --Third, since--.

Line 26, "electron" should read --electrons--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,840,832 B2

No. of add'l. copies
@ 30¢ per page



JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,840,832 B2

DATED : January 11, 2005

INVENTOR(S) : NORIHIRO SUZUKI, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19:

Line 15, "advantage" should read --advantageous--.

DC_MAIN 197310v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,840,832 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)



JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,840,832 B2

DATED : January 11, 2005

INVENTOR(S) : NORIHIRO SUZUKI, ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 46, "and" should be deleted.

COLUMN 2:

Line 50, "to cause." should read --from being caused.--.

COLUMN 13:

Line 37, "film" (second occurrence) should read --films--.

COLUMN 14:

Line 43, "width Ti" should read --width T1--.

COLUMN 16:

Line 31, "electrode 1203" should read --electrodes 1203--.

COLUMN 17:

Line 24, "Third. Since" should read --Third, since--.

Line 26, "electron" should read --electrons--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,840,832 B2

No. of add'l. copies
@ 30¢ per page



JAN 25 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,840,832 B2

DATED : January 11, 2005

INVENTOR(S) : NORIHIRO SUZUKI, ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 19:

Line 15, "advantage" should read --advantageous--.

DC_MAIN 197310v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,840,832 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)



JAN 25 2006